

# Known Anomalies for Patients – Project BFG

Rev A

| Relevant IFU(s) | ID        | Description   | Impact on Safety and Efficacy | Mitigation   |
|-----------------|-----------|---|-------------------------------|--|
| Patient         | MPSYS-6   | The CPM Wearable (Gen 1.6) functions as if it is still charging when the magnetic charging cable is disconnected. The patient will not be able to take a measurement. | 1- Negligible Risk            | Contact the technical support line in the event of inability to take a measurement.  |
| Patient         | MPSYS-344 | Sometimes, at random, the wearable exhibits a low battery percentage, which prevented running the final test or taking a measurement.                                 | 1 - Negligible risk           | If Resetting and charging the wearable does not solve it, it has been found that re-flashed with the same firmware and reprovisioning to the same cloud environment fixes the problem. |
| Patient         | 29488     | Wearable Device communication stuck at device handshake with base station.  | 1-Negligible risk             | Need to unplug and re plug the magnetic cable  |
| Patient         | 29489     | In very rare occasions the base Station is entering into reprovisioning state when kept for overnight.  | 1-Negligible risk             | Contact the technical support line in the event of inability to take a measurement. Base station may have to be replaced.  |